



## ▶ New 'Sentinel' Integrity Monitoring Rockbolt



The **Sentinel** Integrity Monitoring Rockbolt is a new concept in rockbolting safety from Golder RMT. The **Sentinel** is a modified AT rockbolt which can signal to the Mine Rockbolting Engineer whether it is broken and, if so, where.

Bolt failure can occur due to overloading and / or corrosion and when it occurs it can be difficult to detect. We recommend that a row of **Sentinel** bolts is placed across the tunnel at regular intervals as substitutes for the standard rockbolts. The exact spacing would depend upon local circumstances.

An installed **Sentinel** bolt is read by inserting a simple probe connected to an IS strain meter into an environmentally protected sleeved socket at the end of the bolt. The strain meter reading provides a clear indication of the bolt integrity.

The **Sentinel** has undergone extensive testing prior to release. When used in conjunction with Dual Height Telltales, the **Sentinel** provides added confidence in the installed rockbolting system.

We are committed to bringing to the industry the instrumentation and expertise necessary to ensure continued safe use of rockbolting in mines.

For further information please contact:

David Bigby  
Technical Director Instrumentation  
Tel: +44 (0)1283 522201  
Email: [dbigby@golder.com](mailto:dbigby@golder.com)

RMT008-S/07-09 V2

Golder Associates (UK) Ltd  
Trading as Golder RMT

**UK Offices:** Belfast, Bretby, Chelmsford, Edinburgh, Falmouth, Leeds, London, Maidenhead, Nottingham, Oxford.  
**Globally:** Operations across Europe, Africa, Asia, Australasia, North America and South America.

[www.rmtltd.com](http://www.rmtltd.com)  
[www.golder.com](http://www.golder.com)

